
BRINE PRO™ 2000

This "READ ME FIRST" notice is for Brine Pro™ software version 3.0, including:

- HMI Program Version 11082.1
- PLC Program Version 11081.3

If your Brine Pro unit is currently running software versions earlier than those listed above, open the Software Update Installation Instructions included in your download package. That document explains how to identify the versions are currently installed on your unit and gives instructions on how to update the Brine Pro software, if needed.

Major updates included in Version 3:

- Display Revisions
- Simplified Factor Adjustment
- Revisions to Salinity Control Algorithms
- Revised Startup Behavior

This is an extensive update. It should be installed on all Brine Pro units with software versions earlier than those stated above.

SnowEx® Technical Service is available
Monday–Friday from 7:30 to 4:30 (Eastern Time).
Phone: 1-800-725-8377; Option 2

TrynEx International, LLC
531 Ajax Drive, Madison Heights, MI 48071-2429

☛ A DIVISION OF DOUGLAS DYNAMICS, LLC

Software © 2017 by Douglas Dynamics, LLC. All rights reserved. This material may not be reproduced or copied, in whole or in part, in any electronic or other distribution and storage media without the written consent of TrynEx International, LLC.

TrynEx International reserves the right under its product improvement policy to change firmware and software programs and furnish update files when so altered. The following are registered (®) or unregistered (™) trademarks of Douglas Dynamics: Brine Pro™, SnowEx®.

Printed in USA.